## **Annexure D**

## **BUILDING SAFETY CERTIFICATE**

Ma	
No.	Dated: 22-08-2015
	Dated: AZZZZZZ

...... (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the	Three					
Block	floors					

1. However presently by wind inepected the said building seems to be safe for Euning the school for academic session 2025-26 undernormal conditions.

2. except un case of matrical claimities.

3. unequal selfement etc. Also, no skuckusal deaunings were available to a second of the contract of skuckusal deaunings were available to it seems fit for use. Also this cost five your survey on vivual basis

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Executive Engineer
Kalpa Division
HP. PWD, Kalpa

Name & Address of Department/ Office: